

TIMKEN®

THE TIMKEN COMPANY

GENERAL OFFICES

CANTON, OHIO, U.S.A. 44706-2798

TELEPHONE: (216) 438-3000

US EPA RECORDS CENTER REGION 5



494527

July 5, 1989

Mr. Kelvin F. Rogers
Environmental Scientist
Ohio Environmental Protection Agency
Division of Water Pollution Control
Northeast District Office
2110 East Aurora Road
Twinsburg, Ohio 44087

Dear Mr. Rogers:

In regard to the conditions of our monthly monitoring requirements, the following overages were reported for June 1989. On June 5, 1989, pH readings at monitoring stations 901 and 902 were 9.3 and 9.1 respectively. These are the upstream and downstream monitoring stations to our Gambrinus Facility and are not our discharges. On June 21, 1989, a reading of 9.3 pH was found at our outfall 007. The only explanation for this overage is due to the redressing of the various laydown yards in the area. Also, an oil and grease reading at our upstream monitoring station 901 was 72.6 mg/l.

If you have any questions, please call me at (216) 438-3333.

Sincerely,

W. E. Lacure

Environmental Control Coordinator

js/a:1302.wel

RECEIVED

JUL 07 1989

OHIO EPA-N.E.D.O.